



AXL-TEC-19

MODEL 35 INTERNAL PARTS KIT 706967-1X

SERVICE/TECHNICAL

DATE: October 21, 2002

TO: All CVSP Spicer® Light Axle Distributors

Part number 41595 was discontinued. This is a Model 35 cross shaft that has two grooves for snap rings that retain it in the differential case. It was used in internal parts kit, 706967-1X which is discontinued also. This internal parts kit was used to repair differential assembly kits 74210X and 72030-1X in early Jeep Model 35 applications.

Differential assembly kit 74210X is also serviced by internal parts kit 707349X in later Jeep applications. This internal parts kit has a cross shaft with a drilled hole for a shaft lock pin. Use 707349X as an internal parts kit for all listings of the 74210X.

Differential assembly 72030-1X does not have a drilled hole in the case to accept a shaft lock pin, so the 707349X will not service this part. Anyone with a 72030-1X needing an internal parts kit will have to replace the differential assembly with a complete differential assembly kit number 74210X.

Gene Zavrel
Product Manager
Light Axle Products

LIGHT AXLE INFO